


Pav



electric entry here

x = 400 v power socket

turn other way

x electric point outside x electric point outside